

File Name:	Firmware Upgrade	Version	1.0
Project:	Instruction	Update Date:	2019-3-28
Sub Project:	Firmware Upgrade		

GPS Tracker Firmware Upgrade Instruction

V1.0



File Name:	Firmware Upgrade	Version	1.0
Project:	Instruction	Update Date:	2019-3-28
Sub Project:	Firmware Upgrade		

Content

1.	Software Introduction	3
2.	Hardware and Software required	3
3.	Installation and Connection	.3
4.	Firmware Upgrade	4



File Name:	Firmware Upgrade	Version	1.0
Project:	Instruction	Update Date:	2019-3-28
Sub Project:	Firmware Upgrade		

1. Software Introduction

This software is for upgrading firmware for VT900

2. Hardware and Software required

- 2.1 One desktop or laptop, compatible OS: Windows 2000, Windows XP, Windows Vista, Windows 7
- 2.2 One USB data cable
- 2.3 RS232 Driver PL2303_Prolific_DriverInstaller_v1210.exe
- 2.4 Firmware and Firmware_Upgrade_Tool

3. Installation and Connection

3.1 Install RS232 Driver PL2303_Prolific_DriverInstaller_v1210.exe 3.2 Connect USB Data Cable to computer's USB port



3.3 Connect tracker to USB data port.(Note: please do not connect tracker to external power, keep it power off)





File Name:	Firmware Upgrade	Version	1.0
Project:	Instruction	Update Date:	2019-3-28
Sub Project:	Firmware Upgrade		

4. Firmware Upgrade

4.1 Run software Firmware_Upgrade_Tool.

4.2 Check AUTO UPDATE, click button by to choose firmware, then choose right COMPORT OPEN as following picture:

Firmware_Upgrade_Tool_V1.03	•
Config	🗆 Auto Update
Bin File	
1	
	Clear
Process	
	Evit
	EXII

4.3 Connect tracker to USB data cable as above instruction, click "POWER" button for 1sec, two LED on.





File Name:	Firmware Upgrade	Version	1.0
Project:	Instruction	Update Date:	2019-3-28
Sub Project:	Firmware Upgrade		

4.4 Next, the system will pop up a dialog box, click the button as following picture, it enter firmware upgrade mode:

Bin File	· 今期四度 - 井平洋人 - 東北い(TCO0今期)四	向かみまい0010ケ2日1CE
E:\B.技术御义幵:	长走朝程序,技术讨论,要求(VI600走朝程)	序又开关12013年3月16章
T900_3G_V1.75	D8_20190315.bin	
	Notice	83
	Ready Update?	
	是(Y) 否(N)	
		Class
		Clear

4.5 Firmware_Upgrade_Tool window shows "start...", then firmware upgrade proceed automatically, it will show "End" after upgrade complete.

Firmware_Upgrade_Tool_V1.03	Firmware_Upgrade_Tool_V1.03
Config	Config
COM4 Close Auto Update	COM4 Close Close Come
Bin File	Bin File
E:\B.技术部文件夹 定制程序,技术讨论,要求\VT600定制程序文件夹\2019年3月164	E:\B.技术部文件夹 定制程序,技术讨论,要求\VT600定制程序文件夹\2019年3月16撮
▼T900_3G_V1.75_D8_20190315.bin 2019/3/27/星期三, 17:34:48 Start	VT900_3G_V1.75_D8_20190315.bin 2019/3/27/星期三 17:34:48 Start Update Completed Update Completed Update Completed! 通定
Clear	Clear
Process	Process
Exit	Exit
Firmware_Upgrade_Tool_V1.03	
Config	
COM4 Close Cose Cose Cose Cose Cose Cose Cose C	
E:\B.技术部文件夹 定制程序,技术讨论,要求\VT600定制程序文件夹\2019年3月16급	
VT900_3G_V1.75_D8_20190315.bin 2019/3/27/星期三, 17:34:48 Start Update Completed 2019/3/27/星期三, 17:35:20End	
Process	
Exit	



File Name:	Firmware Upgrade	Version	1.0
Project:	Instruction	Update Date:	2019-3-28
Sub Project:	Firmware Upgrade		

Note: if firmware upgrade failed, please read above steps.

If you have any questions, please send e-mail to info@istartek.com. We are here to help you.